



Wellington's Professional Property Managers

1-8 Howard St, Mt Cook, Wellington

Carried out by RentWellington Property Managers on 20 March 2015

Lounge

Brand new paint, carpet, drapes, curtains and lights. No light fittings, just hanging battons.

NO damage, or cracked glass.

Bathroom

Walls

Brand new paint, vinly, shower, and vanity. Net curtain on window.

NO damage, or cracked glass.

Kitchen

Brand new vinly, kitchen cabinets, lights and paint. Stove fully cleaned inside and out. No damage. 1

Hallway

Brand new carpet, no cracked glass in doors. No marks on walls, all new.

Bedroom

Brand new paint, carpet, drapes, curtains and lights. No light fittings, just hanging battons.

NO damage, or cracked glass. Large wardrobe with mirrors.

Tenants Initials Please

RentWellington Property Managers

Level 1, 66 Bay Rd, Kilbirnie

0800 567 563

Service@rentwellington.co.nz - www.RentWellington.co.nz



Wellington's Professional Property Managers

Chattels

Electric stove. Waste pipe in bathroom for washing machin.

Keys provided – Two keys provided. One on kitchen bench and one in letterbox.

Signed as a true description of the property condition as at 20 March 2015

Sign:

Tenants name and signature

Sign:

Tenants name and signature

Please sign this report, initial the bottom right of each page and scan back to
Service@RentWellington.co.nz

Before signing, add above any notes that the property manager has overlooked.

Tenants Initials Please